

Description	Model	Part Number	US\$	Quantity
BLADE, CLEANING	CLC3100	FB2-2887-000	\$11.00	118
CLAW	NP6221	FA6-5433-000	\$2.99	219
CLAW SEPARATION UPPER	NP6080	FA6-4296-000	\$2.99	108
CLEANER SUPPLY ROLL	CLC900	FB2-3482-000	\$18.00	76
DEVELOPING ASSEMBLY	CLC3100	FG5-8611-010	\$59.00	29
DRUM	NP3825	F43-7202-030	\$49.00	10
DRUM	NP3825	F43-2011-040	\$49.00	6
DRUM CLEANING BLADE	CLC900	FB2-0350-000	\$17.00	51
ETHERNET PCB ASSEMBLY	IR5000	FG6-9898-000	\$115.00	1
FIXING FILM ASS'Y	HP LaserJet 3200	RG5-4589-040	\$69.00	78
FIXING FILM ASS'Y	HP LaserJet 6P	RG5-2803-080	\$59.00	74
FIXING HEATER UNIT	IR C3170I	FG3-2791-000	\$69.00	28
FIXING ROLLER LOWER	NP6030	FB1-7957-000	\$49.00	129
MAIN CONTROLLER PCB ASS'Y	IR3320	FG3-2492-000	\$459.00	27
MEMORY PCB ASSEMBLY	CLC1140	FG6-2501-000	\$25.00	21
MOTOR, DC, 1.36W	NP6050	FH5-1138-000	\$26.00	41
MOTOR, STEPPING	NP6030	FH7-1921-000	\$42.00	213
OIL ROLLER	NP6221	FC2-2262-000	\$13.00	73
PRIMARY CORONA ASSEMBLY	CLC900	FG5-5634-050	\$109.00	24
PRIMARY CORONA ASSEMBLY	NP6050	FG5-4378-080	\$79.00	30
PRIMARY CORONA ASS'Y	IR600	FG6-2015-000	\$109.00	12
RING RUBBER	Canon GP55	FA9-0240-000	\$3.00	366
ROLLER A	NP-6650	FF9-0581-030	\$4.00	1048
ROLLER FEED	RDF-C1 NP6030	FE6-3035-020	\$1.90	130
ROLLER FIX UPPER	NP-6650	FA5-7730-000	\$39.00	68
ROLLER FIXING	GP405	FB5-0289-020	\$59.00	125
ROLLER MP TRAY PICK-UP	HP LaserJet6P	RB1-2127-000	\$4.50	195
ROLLER PICK - UP	NP-4835	FA5-2854-030	\$2.30	175
ROLLER PICK-UP	NP6080	FA3-2615-020	\$3.00	152
ROLLER SEPARATION	NP-4835	FA5-2867-020	\$3.00	106
ROLLER TRANSFER	HPLaserJet 4500	RF5-2112-000	\$43.00	15
ROLLER UPPER	HP LaserJet 5N	RB1-3516-020	\$17.00	204
ROLLER A	NP-6650	FA6-1038-020	\$3.00	217
ROLLER B	NP6060	FA6-8089-020	\$2.00	311
ROLLER C	Canon NP3325	FL9-0010-020	\$3.00	103
ROLLER FEEDER	NP-4835	FA5-2933-020	\$5.00	112
ROLLER TRANSFER	GP225	FF5-4565-000	\$65.00	62
ROLLER, CLEANING	CLC1180	FB4-6645-000	\$43.00	75
SEPERATION CLAW (C4228A)	HP Mopier 240	RB1-6613-000	\$2.00	140
SEPERATION ROLLER	NP6080	FL9-0078-030	\$2.00	27
TRANS.SEP.CORONA ASSEMBLY	NP6241	FG5-1204-100	\$85.00	30
TRANSFER CORONA ASSEMBLY	NP6035	FG5-7840-000	\$89.00	18
TRANSFER CORONA ASS'Y	NP6221	FG2-1312-050	\$49.00	15

Drums



Fusers



Toner

